5/029/0007 TASL ID 2708



October 21, 2008

Paul B. Baker, Minerals Program Manager Division of Oil, Gas and Mining 1594 West North Temple Suite 1210 P.O. Box 145801 Salt Lake City, UT 84114-5801

Re:

Deficient Notice of Intention to Commence Small Mining Operations, Granite

Dated September 30, 2008

Morgan Aggregate Facility, S0290007

Response to Letter

Dear Mr. Baker:

In response to your letter dated September 30, 2008, Granite Construction Company (Granite) is enclosing with this letter an updated drawing with a north arrow and scale attached. The original AutoCAD drawing is available if requested.

Also enclosed with this letter is a surety bond in the amount of \$21,900. This bond amount is in line with the amount requested in the Division's deficiency notice.

If you have any questions or comments, please feel free to call me at (801) 526-6047 or by cell phone at (801) 831-6047.

Sincerely,

Chris Faulhaber

Environmental Manager

Granite Construction Company

Utah Operations

CC: Carlos Alegre, Manager of Construction Materials

Enclosures:

(1) Map of Morgan Pit

(1) Surety Bond

RECEIVED

OCT 2 3 2008

DIV. OF OIL, GAS D MIMINIS

